



# AQUANAUT DRIFTER 1100 OK



~ Year built	2005	~ No. of cabins	1
~ Length	11.10 meter	~ No. of beds	2
~ Width	3.50 meter	~ Extra berths	2
~ Draft	1.05 meter	~ Motorization	1x Perkins M135 135 pk (Inboard)
~ Material	Steel	~ Price	€ 142,500,- (TAX paid)
~ Reference	4B086	~ Berth	Friesland, bezichtiging op afspraak



## GENERAL INFORMATION

---

<b>Name of the yacht</b>	Rustpunt	<b>Weight</b>	9,000 kg
<b>Type</b>	Motor yacht	<b>Hullshape</b>	Multi chine
<b>Yard</b>	Aquanaut Sneek	<b>Material window frames</b>	Aluminium

## TECHNICAL EQUIPMENT

---

<b>Running hours</b>	1200	<b>Propeller</b>	4-blade screw
<b>Number of engines</b>	1	<b>Shaft lubrication</b>	Grease lubrication
<b>Drive</b>	Fixed propeller shaft	<b>Steering</b>	Hydraulic
<b>Cooling</b>	Interkoeling	<b>Stabilizers</b>	No
<b>Gearbox</b>	ZF/Scatra	<b>Fuel tank</b>	500 liter Steel
<b>Engine control</b>	Morse	<b>Drinkwatertank</b>	500 liter Stainless steel
<b>Holdingstank</b>	120 liter Stainless steel		
<b>Thruster</b>	Yes, electric 75 Kgf + remote control		
<b>Stern</b>	Yes, electric 95 Kgf + remote control		

## ELECTRIC EQUIPMENT

---

<b>Tension</b>	12V/220V	<b>Converter</b>	No
<b>Generator</b>	Yes, Mastervolt Whisper 3500		
<b>Battery charger</b>	Yes, Mastervolt Mass 12V/80Amp		

## ACCOMMODATION

---

<b>Panelling interior</b>	Cherry	<b>Boiler</b>	Yes, via motor or 220V
<b>Upholstery</b>	Fabric, upholstery in OK 2012	<b>Cooker</b>	Yes, 4-burner gas (2015)
<b>Heating</b>	Yes, Webasto Airtop 3500	<b>Lavatory</b>	Yes, electric

## NAVIGATION

---

<b>VHF Radio</b>	Yes, Raymarine (2015)	<b>GPS</b>	Yes, Raymarine C90W
<b>Radar</b>	Yes, Raymarine		
<b>Depth sounder</b>	Yes, Raymarine ST60 Tridata combination with log		



# MORE INFORMATION ABOUT THIS YACHT?

Ask for the extensive information package!

**Tel.**

+31 (0)6 53 72 52 00

**E-Mail**

[info@jachtmakelaardij4beaufort.nl](mailto:info@jachtmakelaardij4beaufort.nl)

**Website**

[www.jachtmakelaardij4beaufort.nl](http://www.jachtmakelaardij4beaufort.nl)

The content has been compiled with the greatest possible care. However, we do not accept liability for any possible incorrect information displayed herein.